

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Date:

Reviewed:	

July 6, 2010

Elements of Inspection	Evaluated Comment Enforceme	nt		
Other Participants: Josh Nelson, Gordon Jarrett	Mine Status ACT			
Inspector(s): Wayne Western	Time : 9:45am – 11:45 am			
Operator Name: Ash Grove Cement Company	Inspection Date : June 24, 2010			
Mine Name: Leamington Cement Plant	Permit Number: M0230004			

	Elements of Inspection		Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds				
2.	Public Safety (shafts, adits, trash, signs, h	ighwalls)		\boxtimes	
3.	Protection of Drainages / Erosion Control		\boxtimes		
4.	Deleterious Material				
5.	Roads (maintenance, surfacing, dust cont	rol, safety)	\boxtimes	\boxtimes	
6.	Concurrent Reclamation				
7.	Backfilling/Grading (trenches, pits, roads shafts, drill holes)	, highwalls,			
8.	Water Impoundments				
9.	Soils		\boxtimes	\boxtimes	
10.	Re-vegetation		200		
11.	Air Quality				
12.	Other				

Bond Amount: \$4,526,300 **Permit fee**: Up to date

Purpose of Inspection:

Routine annual inspection.

Directions to Site:

The site is approximately 5 miles north of Leamington, Utah on highway 132. One can see the plant from the road.

Inspection Summary:

- 1. The bond amount is adequate and the permit fees are up to date.
- 2. The highwalls appeared stable. No sign of failures were present.
- 3. The site is a total containment site. No sign that water had left the site.
- 9. The Permittee should make every effort to salvage topsoil if the expansion is approved.
- 12. The Permittee is in the process of expanding the pit towards the south. We visited the area and looked at the exploration work.

Inspection Date: June 24, 2010

Page 2 of 3 M/023/0004

Conclusions and Recommendations:


The Division should continue to monitor the site.

Inspector's Signature MMW

cc: Ash Grove Cement Plant

Mike Okuniewiez, MSHA Okuniewiez.Michael@dol.gov

O:\M023-Juab\M0230004-Leamington\Inspections\ins_Leamington_07142009.doc



Highwalls